

Update on My Work - February 2018

Path	Status	Problem	Current Action	Hermis / Confirm no.
3	FP	Uninformative / misleading signs across golf course	Will discuss with golf course manager	10207157
4	BR	Plastic covers over route, maybe over a trench, concerns over horses passing over these, their weight and slippery for them	Contacted National Grid to find out why they are there and raise safety concerns. They are investigating	10206683 In progress
5	FP	Waymark post uprooted at junction with footpath 2	contacted golf club, asked CMS vols to re-install	10207130 On order
5	FP	Waymark post uprooted near wood	contacted golf club, now reinstalled	10207131 Done
11	FP	Broken stile	Contacted landowner about removal as not required for stock, stile has now been replaced with new one, will contact landowner again, as not authorised or authorisable	228343
13	FP	Collapsing barbed wire fence	Need to contact landowner	10206760
14	BOAT	Rutts in surface	Need to inspect	10206874
14	BOAT	Fly tipping	Need to check removed by BC	2237057

16	FP	Trees planted in footpath now narrowing the width	will write to house / land owner and as they are removed	10207159
18	BR	Security camera installed on bridleway	Discussing with Enforcement Officer	10204353
18	BR	Fencing installed in bridleway	Discussing with Enforcement Officer	10204354
19	FP	New fence being installed in footpath	Measured and contacted landowner, width being discussed, walkers may make MOD app for width claim, no further information or App received	10203603 Noted
23	BOAT	Surface rutted and muddy	Need to inspect	10206875
23	BOAT	Missing sign at roadside	Will add to next signage schedule	10206876
24	FP	Broken stile near Waste site	discussing with landowner	10206877
24	FP	rubbish on route near Waste site	discussing with landowner	10206878
24	FP	new fence obstruction near Waste site	discussing with landowner	10206879
25	BR	Golf balls from new driving range being hit across bridleway, near miss with a horse and rider	Need to contact golf course	10205254